



• INFORMATION BULLETIN •
AUTOMOTIVE PARTS DIVISION
PARTS PUBLICATIONS



ISSUED: 5-1-69

PLEASE MAKE THE FOLLOWING CHANGES TO YOUR F-14063 PARTS CATALOG:

Group No. 3.031, Page No. Gr 3 - 18; Delete All Information And Insert The Following Information In Its Place:

60 Thru 62 01 (LHE): 60 Thru 62 20-80.....	1	320 1801
60 Thru 62 01-10 (OHV) (American Mtrs: Optional With 448 6723).....	1	320 2807
60 Thru 62 01-10 (OHV) (Delco-Remy: Optional With 320 2807).....	1	448 6723
63 Thru 65 01-10 (Six): 65 80 (OHVC-232) (American Mtrs: Optional With 448 6720).....	1	320 4202
63 Thru 65 01-10 (Six): 65 80 (OHVC-232) (Delco-Remy: Optional With 320 4202).....	1	448 6720
63 Thru 65 10-80 (V8) (American Mtrs: Optional With 448 6721).....	1	320 0197
63 Thru 65 10-80 (V8) (Delco-Remy: Optional With 320 0197).....	1	448 6721
162-63 10 (Can): 164-65 01-10-80 (Can).....	1	320 1801
165 01-10 (OHV-199-Can): 165 01-10-80 (OHV-232-Can).....	1	320 9165

Page No. IL 9 - 3; In The Alphabetical Code Explanation At The Side Of The Page, Delete (N) Part Of SHAFT 9.036.

Page No. IL 9 - 14; After The Alphabetical Code Explanation (N) Part Of NUT 9.050 At The Side Of The Page, Add Alphabetical Code And Explanation (O) Part Of BLOCK 9.039.

Page Numbers IL 9 - 3 AND IL 9 - 14; There Are Four Alphabetical Code Designations Listed For The Two Pinion Shaft Thrust Blocks And Pin. Change The Alphabetical Codes From (D)(H)(N)(O) To (D)(H)(O) For All Three Parts.

The Two Differential Shafts Have Alphabetical Code Designations Of (D)(H)(N). Change The Alphabetical Codes To (D)(H) SHAFT 9.036 For Both Parts.

Group No. 9.036, Page No. Gr 9 - 8; Change Quantity On Part Number 320 0810 From 1 To 2.

Group No. 10.055, Page No. Gr 10 - 10; On Part Number 317 1493, Change Listing To Read:

64-65 01: 65 10-50-80.....	2	317 1493
----------------------------	-------	---	----------