



• INFORMATION BULLETIN •
 AUTOMOTIVE PARTS DIVISION
 PARTS PUBLICATIONS



FORM NO. 2-1-54

PLEASE MAKE THE FOLLOWING CHANGES TO YOUR F-14083 PARTS CATALOG:

Group No. 2.031, Page No. Cr 3 - 18; Delete All Information And Insert The Following Information In Its Place:

60 thru 62 01 (LME): 60 thru 62 20-80	I	320 1801
60 thru 62 01-10 (ENV) (American Mfrs: Optional With 448 6723)	I	320 2803
60 thru 62 01-10 (OHV) (Delco-Remy: Optional With 320 2803)	I	448 6723
62 thru 62 01-10 (Six): 62 80 (OHV-232) (American Mfrs: Optional With 448 6720)	I	320 4202
62 thru 62 01-10 (Six): 62 80 (OHV-232) (Delco-Remy: Optional With 320 4202)	I	448 6720
62 thru 62 10-80 (V8) (American Mfrs: Optional With 448 6721)	I	320 0197
62 thru 62 10-80 (V8) (Delco-Remy: Optional With 320 0197)	I	448 6721
162-63 10 (Cam): 162-63 01-10-80 (Cam)	I	320 1801
162 61-10 (OHV-199Cam): 162 01-10-80 (OHV-199Cam)	I	320 9183

Page No. II 9 - 17 In The Alphabetical Code Explanation At The Side Of The Page, Delete (M) Part Of Block 9.036.

Page No. II 9 - 16; After The Alphabetical Code Explanation (M) Part Of Block 9.036 At The Side Of The Page, Add Alphabetical Code And Explanation (O) Part Of Block 9.037.

Page Numbers II 9 - 17 AND II 9 - 16; There Are Four Alphabetical Code Designations Listed For The Two Pinion Shafts (Lower Blocks And Pin Change The Alphabetical Codes From (D)(H)(M)(O) To (D)(H)(O) For All Three Parts.

The Two Differential Shafts Have Alphabetical Code Designations Of (D)(H)(O). Change The Alphabetical Codes To (D)(H) SHAFTS 9.036 For Both Parts.

Group No. 9.036, Page No. Cr 9 - 8; Change Quantity On Part Number 320 1801 From 1 To 2.

Group No. 9.035, Page No. Cr 10 - 10; On Part Number 315 1801, Change Listing To Read:

62-10-80-00..... I 315 1801